



GROUP G

	GROUP G				
	SCRATCH		DENT		REPLACEMENT BREAKING MISSING PART
	LIGHT	SERIOUS	LIGHT	SERIOUS	
BODYWORK					
Front fender	€ 240	€ 355	€ 315	€ 560	€ 850
Rear fender	€ 240	€ 385	€ 385	€ 625	€ 1.100
Front door	€ 240	€ 395	€ 395	€ 760	€ 1.400
Rear door	€ 240	€ 395	€ 395	€ 760	€ 2.500
Sill	€ 120	€ 300	€ 230	€ 395	€ 680
Front hood	€ 185	€ 350	€ 315	€ 450	€ 785
Rear hood or talgate	€ 185	€ 400	€ 325	€ 505	€ 1.300
Roof	€ 295	€ 395	€ 350	€ 570	€ 1.680
Front bumper	€ 200	€ 400	€ 220	€ 395	€ 600
Rear bumper	€ 200	€ 400	€ 220	€ 395	€ 600
Manual external rearview (excluding glass)	€ 60	€ 145	€ 145	€ 205	€ 315
Electric external rearview (excluding glass)	€ 110	€ 220	€ 220	€ 370	€ 495
Car door handle (Lock <u>NOT</u> damaged)	€ 80	€ 135	€ 135	€ 250	€ 330
Plate	€ 25	€ 50	€ 35	€ 50	€ 500
Fuel cap	€ 50	€ 150	€ 50	€ 150	€ 500
Internal rearview mirror	€ 120				
Front bumper moulding	€ 500				
Rear bumper moulding	€ 300				
Sill moulding	€ 300				
Front fender moulding	€ 200				
Rear fender moulding	€ 200				
Lock or Key	€ 280				
Car emblem	€ 50				
RIMS AND TYRES					
Alloy rims	€ 85	€ 165	€ 165	€ 165	€ 495
Iron rims	€ 55	€ 110	€ 135	€ 135	€ 135
Hubcap	€ 45	€ 55	€ 55	€ 60	€ 70
Tyre	€ 325				
Kit tyre repair	€ 195				
GLASSES					
Front door glass	€ 330				
Rear door glass	€ 470				
Front and rear door fixed glass	€ 495				
Rear window	€ 550				
Windscreen	€ 770				
Glass ceiling	€ 1.100				
Rearview mirror glass (interior)	€ 80				
Side turn indicator	€ 50				
Headlamp (NO xenon headlights)	€ 440				
Headlamp (xenon headlights / led)	€ 1.100				
Fog lamp	€ 220				
Rear light assembly	€ 330				
INTERIORS					
Extra wash	€ 80				
Veichle sanification	€ 90				
Upholstery and interior finishes	€ 220				
Hatbox surface	€ 100				
High visibility jacket	€ 25				
Warning triangle	€ 25				
Car documents	€ 200				
Smoking ban violation	€ 100				